QUALITY CONTROL

BR No: 450/13-14 D: 31-10-13

Name of the Work: Construction of Anganawadi building at Karekallu village Vinayaka Nagara in W. NO-14

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed 2 years back.

Assistance Executive Engineer
Dasarahalli Sub Division
Bruhat Bengaluru Mahanagara Palike

19/2/15

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike